

HEALTH & WELFARE

DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@dhw.idaho.gov

July 22, 2010

Cliff McAleer, Administrator Milestone Decisions Inc. #2 (6th Street) 611 South Main Moscow, Idaho 83843

RE: Milestone Decisions Inc. #2 (6th Street), Provider #13G019

Dear Mr. McAleer:

This is to advise you of the findings of the Medicaid/Licensure Fire Life Safety Survey, which was concluded at Milestone Decisions Inc. #2 (6th Street), on July 13, 2010.

Enclosed is your copy of a Statement of Deficiencies/Plan of Correction, form CMS-2567, which states that no Medicaid deficiencies were noted at the time of the survey. Also, enclosed is a similar form stating that no State licensure deficiencies were noted at the time of the survey.

Thank you for the courtesies extended to us during our visit. If we can be of any help to you, please call our office at (208) 334-6626.

Sincerely,

TAYLOR BARKLEY

Juph BM

Health Facility Surveyor

Facility Fire Safety and Construction Program

TB/li

Enclosure

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 07/21/2010 FORM APPROVED OMB NO. 0938-0391

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

, , ,			. SIXTH STREET OW, ID 83843			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 000	INITIAL COMMENTS		K 000			
	The facility is a single story, type V (III) built in 1983. The facility is protected by automatic fire sprinkler system with system sprinkler heads in habitable spaces. The complete fire alarm/smoke detection sy installed. Currently the building is licens ICF-MR beds.	y a 13 D tem nere is a estem				
	The facility was found to be in substanticompliance with applicable fire/life safe requirements set forth in the Life Safety 2000 edition, Chapter 33, Existing Resil Board and Care Occupancy, Impractical Evacuation Capability. The survey was conducted on July 13, 2010, in accordance 42 CFR 483.470.	ty Code, dential				
, i	The annual life safety code survey was by:	conducted				
	Taylor Barkley Health Facility Surveyor Facility Fire Safety & Construction Prog	ıram			***	
		3				
		W.	r.			
		ŕ	To a se			
		į				
	RY DIRECTOR'S OR PROVIDER/SUPPLIER REPRES			TITLE	(X6) DATE	

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

PRINTED: 07/21/2010 FORM APPROVED

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION

(X3) DATE SURVEY COMPLETED

13G019

A, BUILDING 02 B. WING _

07/13/2010

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

MILESTONE DECISIONS INC #2 (6TH ST)

1430 E. SIXTH STREET

MILESTONE DECISIONS, INC. #2 (6TH ST)			1430 E. SIXTH STREET MOSCOW, ID 83843				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENC (EACH DEFICIENCY MUST BE PRECEDED E REGULATORY OR LSC IDENTIFYING INFOR	BY FULL	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETS DATE		
М 000	16.03.11 Inital Comments		M 000				
or reducing	The facility is a single story, type V (III built in 1983. The facility is protected automatic fire sprinkler system with sysprinkler heads in habitable spaces. complete fire alarm/smoke detections installed. Currently the building is lice ICF-MR beds. The facility was found to be in substar	by a 13 D rstem There is a system nsed for 8					
	compliance with applicable fire/life safe requirements set forth in the Life Safe 2000 edition, Chapter 33, Existing Research and Care Occupancy, Impractic Evacuation Capability. The survey was conducted on July 13, 2010, in according Index according to the Mentally Retard (ICF-MR).	ety ty Code, sidential cal as dance with ermediate					
	The annual life safety code survey wa conducted by: Taylor Barkley	s					
	Health Facility Surveyor Facility Fire Safety & Construction Pro	gram					
	V DIDECTOR'S OR DROVINER/SLIDBLIED REDRES			Tritic	(X6) DATE		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE